

5971/5972 Top Board Repair

We can repair your HP 5971 or 5972 Top board (05971-60001) at our service depot, often for much less than replacing or exchanging the board !

Getting "Difficulty in the Mass Filter Electronics" error ?

"Gain and offset = 0 and peaks are too wide" error ?

"Cannot achieve constant peak width" error ?

"No peaks found" error ?

These errors can point to your top board. Send us your board today, for evaluation and quote.

We also have board level troubleshooting capability for other 5971/5972 boards (Main Board, PDB, DC Power Supply).

We can also troubleshoot other model boards - 5970, 5988, and 5989 .

[Click here to contact a CSSCO specialist about your repair needs!](#)